03/12-11/67/97-01767

#### FINAL

## REMEDIAL INVESTIGATION REPORT SITE 73 - AMPHIBIOUS VEHICLE MAINTENANCE FACILITY

### **FIGURES**

MARINE CORPS BASE CAMP LEJEUNE, NORTH CAROLINA

CONTRACT TASK ORDER 0312

NOVEMBER 7, 1997

Prepared For:

DEPARTMENT OF THE NAVY ATLANTIC DIVISION NAVAL FACILITIES ENGINEERING COMMAND Norfolk, Virginia

Under:

LANTDIV CLEAN Program Contract N62470-89-D-4814

Prepared by:


BAKER ENVIRONMENTAL, INC. Coraopolis, Pennsylvania


# LIST OF FIGURES


1-1	Location Map
1-2	Site Map
1-3	UST Location Map
1-4	Confirmation Study Sample Location Map
1-5	UST SA-21 (ATEC, 1991) Sample Location Map
1-6	UST SA-21 (Baker, 1992) Sample Location Map
1-7	TPH (Low-Med) Concentrations in Soils (Baker, 1992)
1-8	TPH (Med-High) Concentrations in Soils (Baker, 1992)
1-9	Benzene and Total VOC Concentrations in Groundwater (Baker, 1992)
1-10	UST SA-21 (Baker, 1993) Sample Location Map
1-11	TPH (Low-Med) Concentrations in Soils (Baker, 1993)
1-12	TPH (Med-High) Concentrations in Soils (Baker, 1993)
1-13	UST A47/3 (Law-Catlin, 1993) Sample Location Map
1-14	TPH Concentrations - Soil (Catlin Associates, 1993)
1-15	Total BTEX Concentrations - Water (Catlin Associates, 1993)
1-16	Aerial Photograph, February 1, 1956
1-17	Aerial Photograph, October 4, 1970
1-18	Aerial Photograph, February 15, 1983
l-19	Aerial Photograph, March 6, 1998
1-20	Estimated Limits of Contamination Based on Groundwater Screening Results
1-21	Estimated Limits of Contamination Based on Soil Gas Results
1-22	AOC Location Map
2-1	Sampling Locations
2-2	Typical Type II Well Construction Diagram
2-3	Typical Type III Well Construction Diagram (Shallow-Intermediate)
2-4	Typical Type III Well Construction Diagram (Intermediate)
2-5	Typical Type III Well Construction Diagram (Deep)
3-1	Location of Hydrogeologic Cross-Sections, MCB Camp Lejeune
3-2	Hydrogeologic Cross-Sections of the MCB Camp Lejeune Area
3-3	Location of Site Hydrogeologic Cross-Sections
3-4	Hydrogeologic Cross-Section A-A' & B-B'
3-5	Hydrogeologic Cross-Section C-C' & D-D'
3-6 3-7	Groundwater Contour Map Depicting Flow in the Surficial Aquifer
,-,	Groundwater Contour Map Depicting Flow in the Uppermost Portion of the Castle Hayne Aquifer
8-8	Groundwater Contour Map Depicting Flow in the Uppermost Portion of the Castle Hayne
-	Aquifer
-9	Supply Well Location Map
-10	Biohabitat Map
-11	Surface Tonography Man

# LIST OF FIGURES (Continued)


- 4-1 Detected Volatiles (Methods 8240 and CLP), Semivolatiles (Method 8270), and Pesticides/PCBs (Method 8080) in Surface Soils
- 4-2 Detected Inorganics Exceeding 2X Base Background in Surface Soils
- 4-3 Detected Volatiles (Method 8240/8240A), Semivolatiles (Method 8270), and Pesticides/PCBs (Method 8080) in Subsurface Soils
- 4-4 Detected Inorganics Exceeding 2X Base Background in Subsurface Soils
- 4-5 Detected Volatiles (Method 601/602) and Semivolatiles (Method 625) in the Uppermost Portion of the Surficial Aquifer (Phase I)
- 4-6 Detected Volatiles in the Uppermost Portion of the Surficial Aquifer via CLP Method (Phase II)
- 4-7 Detected Inorganics Exceeding NCWQS and/or Federal MCLs in the Uppermost Portion of the Surficial Aquifer (Phase I)
- 4-8 Detected Volatiles (Method 601/602) and Semivolatiles (Method 625) in the Lowermost Portion of the Surficial Aquifer (Phase I)
- 4-9 Detected Volatiles in the Lowermost Portion of the Surficial Aquifer via CLP Method (Phase II)
- 4-10 Inorganics Exceeding NCWQS and/or Federal MCLs in the Lowermost Portion of the Surficial Aquifer (Phase I)
- 4-11 Detected Volatiles in the Uppermost Portion of the Castle Hayne Aquifer via Method 601/602 (Phase I)
- 4-12 Detected Volatiles in Uppermost Portion of the Castle Hayne Aquifer via CLP Method (Phase II)
- 4-13 Detected Inorganics Exceeding NCWQS and/or Federal MCLs in the Uppermost Portion of the Castle Hayne Aquifer (Phase I)
- 4-14 Detected Volatiles (8240), Semivolatiles (Method 8270), Pesticides/PCBs (Method 8080) in Sediment
- 4-15 Detected Inorganics in Sediment via CLP Method
- 4-16 Analytical Results for Surface Water
- 4-17 Isoconcentration Map Defining VOC Detections in the Lower Portion of the Surficial Aquifer and Upper Portion of the Castle Hayne Aquifer
- 4-18 Isoconcentration Map Defining VOC Detections in the Upper Portion of the Surficial Aquifer
- 6-1 Conceptual Site Model for Current and Future Receptors
- 6-2 Probability Distribution of Blood Lead Levels Site 73 Aquatic Biota Exposure
- 7-1 Conceptual Exposure Model for Ecological Receptors
- 7-2 Surface Water and Sediment Quotient Ratio Excedences










01767V03Y








01767 VBIY































312502PP

FIGURE 1-16
AERIAL PHOTOGRAPH, FEBRUARY 1, 1956
SITE 73 - AMPHIBIOUS VEHICLE MAINTENANCE FACILITY
REMEDIAL INVESTIGATION, CTO-0312
MARINE CORPS BASE, CAMP LEJEUNE
NORTH CAROLINA

01767 VB3Y






FIGURE 1-17
AERIAL PHOTOGRAPH, OCTOBER 4, 1970
SITE 73 - AMPHIBIOUS VEHICLE MAINTENANCE FACILITY
REMEDIAL INVESTIGATION, CTO-0312
MARINE CORPS BASE, CAMP LEJEUNE
NORTH CAROLINA





Bakar Environmental, no.





FIGURE 1-18
AERIAL PHOTOGRAPH, FEBRUARY 15, 1983
SITE 73 - AMPHIBIOUS VEHICLE MAINTENANCE FACILITY
REMEDIAL INVESTIGATION, CTO-0312
MARINE CORPS BASE, CAMP LEJEUNE
NORTH CAROLINA











FIGURE 1-19
AERIAL PHOTOGRAPH, MARCH 6, 1993
SITE 73 - AMPHIBIOUS VEHICLE MAINTENANCE FACILITY
REMEDIAL INVESTIGATION, CTO-0312
MARINE CORPS BASE, CAMP LEJEUNE
NORTH CAROLINA











TYPICAL SHALLOW TYPE II


WELL CONSTRUCTION DIAGRAM

SITE 73-AMPHIBIOUS VEHICLE MAINTENANCE FACILITY

REMEDIAL INVESTIGATION, CTO-0312

MARINE CORPS BASE, CAMP LEJEUNE

NORTH CAROLINA




N.T.S.




### FIGURE 2-3

TYPICAL TYPE III WELL
CONSTRUCTION DIAGRAM (SHALLOW-INTERMEDIATE)
SITE 73-AMPHIBIOUS VEHICLE MAINTENANCE FACILITY
REMEDIAL INVESTIGATION, CTO-0312
MARINE CORPS BASE, CAMP LEJEUNE
NORTH CAROLINA




# TYPICAL TYPE III WELL CONSTRUCTION DIAGRAM (INTERMEDIATE) SITE 73-AMPHIBIOUS VEHICLE MAINTENANCE FACILITY REMEDIAL INVESTIGATION, CTO-0312 MARINE CORPS BASE, CAMP LEJEUNE NORTH CAROLINA





TYPICAL TYPE III WELL
CONSTRUCTION DIAGRAM (DEEP)
SITE 73-AMPHIBIOUS VEHICLE MAINTENANCE FACILITY
REMEDIAL INVESTIGATION, CTO-0312
MARINE CORPS BASE, CAMP LEJEUNE

MARINE CORPS BASE, CAMP LEJEUNE NORTH CAROLINA



171-71105V







A---A' - CROSS-SECTION TRAVERSE LOCATION

MW-1 − EXISTING TYPE II GROUNDWATER MONITORING WELL INSTALLED BY ATEC ASSOC., AUGUST 1991

-9 - SHALLOW TYPE I! GROUNDWATER MONITORING WELL INSTALLED BY BAKER ENVIRONMENTAL, INC., MAY 1992

DW-1 - DEEP TYPE III GROUNDWATER MONITORING WELL INSTALLED BY BAKER ENVIRONMENTAL, INC., MAY 1992


SB-1 - SOIL BORING INSTALLED BY BAKER ENVIRONMENTAL,  $\P$  INC., MAY 1992


FIGURE 3-3
CROSS-SECTION LOCATION
SITE 73


AMPHIBIOUS VEHICLE MAINTENANCE FACILITY CTO - 0312


MARINE CORPS BASE, CAMP LEJEUNE NORTH CAROLINA


01767V07Y



















1717110V





















































01767 VB6Y





FIGURE 6-1

## CONCEPTUAL SITE MODEL FOR CURRENT AND FUTURE HUMAN RECEPTORS SITE 73 - AMPHIBIOUS VEHICLE MAINTENANCE FACILITY REMEDIAL INVESTIGATION, CTO-0312 MCB, CAMP LEJEUNE, NORTH CAROLINA






Figure 6-2
Probability Distribution of Blood Lead Levels - Site 73 Aquatic Biota Exposure
Site 73 - Amphibious Vehicle Maintenance Facility
Remedial Investigation, CTO-0312
MCB, Camp Lejeune, North Carolina

## CONCEPTUAL EXPOSURE MODEL FOR ECOLOGICAL RECEPTORS SITE 73 - AMPHIBIOUS VEHICLE MAINTENANCE FACILITY REMEDIAL INVESTIGATION, CTO-0312 MCB, CAMP LEJEUNE, NORTH CAROLINA

