well

From: Director, Hazardous Waste and Pollution Control Division

To: Base Maintenance Officer (AT: VT/)Ties Director)

Subj: SAMPLING OF CONTAMINATED WATER WELLS

Doc. Nb.: CLEJ-00375-3:04-

Ref: (a) BMO memo 11330 MAIN of 14 Jun 90

100/01/90

- 1. The Installation Restoration Program will be resampling some of the contaminated water wells mentioned in your 14 June 1990 memorandum. The wells that will be resampled will be 660 (formerly 601), 603, 642, 602, 608, 630, 634, 637, and 652. The IR Program feels these wells might possibly have been contaminated by previous hazardous waste dumping. Wells TT-23, TT-25, and TT-26 will be resampled by EPA at a later date.
- 2. In order for the IR contractor to resample these wells, the following information will be needed:
  - --current condition of well
  - --logistics of obtaining the samples
  - -- condition of equipment on the well if any

This information is needed as soon as possible. The contractor will be out in the field the month of January with anticipated sampling of these water wells as early as 7 January 199.

3. If there are any questions, please call Stephany Del Re'-Johnson, extension 5093.

DD 5

acls eno