



UNITED STATES MARINE CORPS  
MARINE CORPS BASE  
PSC Box 20004  
Camp Lejeune, North Carolina 28542-0004

PERMANENT FILE

In reply refer to:

5090/15

BEMD

MAR 9 6 2005

Mr. Bruce Reed  
North Carolina Department of Environment  
and Natural Resources  
Division of Waste Management UST Section  
127 Cardinal Drive  
Wilmington, North Carolina 28405-3845

Dear Mr. Reed:

The Soil Contamination Report for the Rapid Refueler Pipeline Repair Site at Building AS-4106 is enclosed for your review. This site is located aboard Marine Corps Air Station, New River, North Carolina.

A petroleum release associated with the fuel transfer pipeline from the Bulk Fuel Farm to the Rapid Refueler System was first discovered on January 10, 2005 during a routine test of the airport hydrant system piping. Most recent sample analytical results indicate soil contamination is below the North Carolina Residential Maximum Soil Contaminant Concentration requirements.

If you have additional questions or need further information, please contact Ms. Nikki Hall, Environmental Quality Branch, Environmental Management Division, Installations and Environment Department, at (910) 451-9610.

Sincerely,

SCOTT A. BREWER, PE  
Director, Environmental Management  
By direction of  
the Commanding General

Enclosure: Rapid Refueler Pipeline Repair Soil Contamination  
Report Building AS-4106 March 2005

Copy to: (w/o encl)  
NAVFACENGCOM (Mr. Cleland Code OPCEV4)

**SOIL CONTAMINATION REPORT  
RAPID REFUELER PIPELINE REPAIR  
BUILDING AS4106  
MARINE CORPS AIR STATION  
CAMP LEJEUNE, NORTH CAROLINA**

Prepared for:

Department of the Navy, Atlantic Division



Naval Facilities Engineering Command  
6506 Hampton Boulevard  
Building A (South East Wing) 3<sup>rd</sup> Floor  
Norfolk, Virginia 24311-6287

Prepared by:



11560 Great Oaks Way, Suite 500  
Alpharetta, GA 30022-2424

Shaw Project No. 109972  
March 2005

EDCL