

06.01 - 08/03/94-01316



DEPARTMENT OF THE NAVY
ATLANTIC DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
1510 GILBERT ST
NORFOLK VA 23511-2699

TELEPHONE NO:

(804) 322-4818

IN REPLY REFER TO:

5090

18232:KHL:cag

AUG 03 1994

CERTIFIED MAIL RETURN RECEIPT REQUESTED

North Carolina Department of Environment,
Health, and Natural Resources
Attn.: Mr. Patrick Watters
P.O. Box 27687
401 Oberlin Road
Raleigh, NC 27611

Re: MCB Camp Lejeune Response to NC DEHNR Comments
Draft Interim Record of Decision Operable
Unit No. 10 (Site 35)

Dear Mr. Watters:

Enclosed are Navy/Marine Corps responses to your comments on the above referenced document. The draft final version of the documents (issued July 20, 1994) incorporate these comments.

Please direct any questions to Ms. Katherine Landman at (804) 322-4818.

Sincerely,

A handwritten signature in cursive script, appearing to read "L. A. Boucher".

L. A. BOUCHER, P.E.

Head

Installation Restoration Section
(South)

Environmental Programs Branch
Environmental Quality Division
By direction of the Commander

Enclosure

Copy to:

EPA Region IV (Ms. Gena Townsend)

MCB Camp Lejeune (Mr. Neal Paul)

Baker Environmental, Inc. (Mr. Ray Wattras, Mr. Dan Bonk)

Activity Admin Record File

**RESPONSE TO COMMENTS SUBMITTED BY NC DEHNR
DRAFT INTERIM RECORD OF DECISION
OPERABLE UNIT #10 (SITE 35)
MCB CAMP LEJEUNE, NORTH CAROLINA**

Comment letter by Mr. Patrick Watters dated June 30, 1994.

1. General

The Draft ROD has been modified as per the comment. RAA 5 (Source Removal and Off-Site Soil Recycling) was selected as the final remedy for the subject site. It was chosen over RAA 6 (Source Removal and On-Site Low Temperature Thermal Desorption) because it is anticipated it will be more cost effective. Although RAA 3 (Source Removal and Off-Site Biotreatment) is estimated to be roughly equal to RAA 5 in cost, RAA 3 was not selected as the preferred alternative because there are more available off-site commercial soil recycling facilities (RAA 5) than biotreatment facilities (RAA 3). Consequently, RAA 5 should be easier to implement. However, if a suitable soil recycling facility is not available at the time of remediation, a biotreatment facility may be substituted as an alternative, subject to the approval of a modification to the Interim ROD.

18232 (KHL)

P 075 318 732

Receipt for Certified Mail



No Insurance Coverage Provided
Do not use for International Mail
(See Reverse)

NC DEPT OF ENVIRONMENT	
MR PATRICK WATERS	
PO BOX 27687 401 OBERLIN RD	
RALEIGH NC 27611	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date, and Address of Addressee	
TOTAL Postage & Fees	\$
Postmark or Date	

PS Form 3800, June 1991

Fold at line over top of envelope to the right of the return address

CERTIFIED

P 075 318 732

MAIL

Is your RETURN ADDRESS completed on the reverse side?

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, and 4a & b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

- Addressee's Address
- Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:
 NC DEPT OF ENVIRONMENT
 MR PATRICK WATERS
 PO BOX 27687
 401 OBERLIN RD
 RALEIGH NC 27611

4a. Article Number
 P 075 318 732

4b. Service Type
 Registered Insured
 Certified COD
 Express Mail Return Receipt for Merchandise

7. Date of Delivery

5. Signature (Addressee)

8. Addressee's Address (Only if requested and fee is paid)

6. Signature (Agent)

PS Form 3811, December 1991

U.S. GPO: 1982-323-402

DOMESTIC RETURN RECEIPT

Thank you for using Return Receipt Service.