



UNITED STATES MARINE CORPS

MARINE CORPS BASE
PSC BOX 20004
CAMP LEJEUNE, NORTH CAROLINA 28542-0004

IN REPLY REFER TO:
5090.10
BEMD

NOV 29 2007

Mr. Bruce Reed
North Carolina Department of Environment
and Natural Resources
Division of Waste Management
Underground Storage Tank Section
127 Cardinal Drive
Wilmington, North Carolina 28405-3845

Dear Mr. Reed:

Enclosed is the Groundwater Sampling Report of Findings for Site H-30. We invite your comments regarding this report.

If you have any questions or require further information, please contact Mr. Andrew Smith, Environmental Quality Branch, Environmental Management Division, Installations and Environment Department, at (910) 451-9017.

Sincerely,

A handwritten signature in black ink, appearing to read "John R. Townson".

JOHN R. TOWNSON
Director, Environmental Management
By direction of
the Commanding Officer

Enclosure: Groundwater Sampling Report of Findings for Site H-30 Marine Corps Base Camp Lejeune

Copy to: (w/o encl)
NAVFACENGCOM (Mr. Dan Oros Code OPCEV4)
Catlin (Mr. Mike E. Mason)✓



PERMANENT FILE

UNITED STATES MARINE CORPS
MARINE CORPS BASE
PSC Box 20004
Camp Lejeune, North Carolina 28542-0004

In reply refer to:
5090/15
BEMD

JAN 28 2005

Mr. Bruce Reed
North Carolina Department of Environment
and Natural Resources
Division of Waste Management
Underground Storage Tank Section
127 Cardinal Drive
Wilmington, North Carolina 28405-3845

Dear Mr. Reed:

Marine Corps Base, Camp Lejeune would like to request an extension of the due dates for the Notice of Regulatory Requirements (NORR) letters listed below. The following table contains a summary of pertinent information:

Site Name	NORR Imposed Due Date	Requirement
820	2/28/2005	<input type="checkbox"/> Sample wells MW3, MW6, and PW1 <input type="checkbox"/> Soil sampling <input type="checkbox"/> Well installation <input type="checkbox"/> System modification based on sample results
H30	2/11/2005	<input type="checkbox"/> Soil excavation

These sites are funded by the Environmental Restoration Navy account. We expected funding prior to December 2004; however, funds were not received until mid-January 2005. This delay caused the schedule to slip, so we do not expect fieldwork to start until late February. We should be able to forward the required information to you by June 17, 2005.

As always, we appreciate your understanding in these matters and will try to get the information to you as quickly as possible. If you have questions or require more information, please contact Ms. Nikki Hall, Environmental Quality Branch, Environmental Management Division, Installations and Environment Department, at (910) 451-9610.

Sincerely,

SCOTT A. BREWER, PE
Director, Environmental Management
By direction of
the Commanding General

For

PERMANENT FILE



UNITED STATES MARINE CORPS
MARINE CORPS BASE
PSC Box 20004
Camp Lejeune, North Carolina 28542-0004

In reply refer to:
5090/15
BEMD

▶ JUN 16 2005

Mr. Bruce Reed
North Carolina Department of Environment
and Natural Resources
Division of Waste Management
Underground Storage Tank Section
127 Cardinal Drive
Wilmington, North Carolina 28405-3845

Dear Mr. Reed:

Enclosed is Former Building H-30 Soil Removal Report for your review. The report addresses the recent soil removal activity completed at the site. Please provide us with your comments and/or approval.

Former Building H-30 is located in the Hospital Point area of Marine Corps Base, Camp Lejeune, North Carolina. On May 18, 2005, soil removal activities were completed at the site. The area measured approximately 10 feet by 10 feet and was approximately four (4) feet deep. A total of approximately 20 tons of soil was removed during the removal action.

Sidewall confirmation samples and a floor confirmation soil sample were collected from the excavation on May 18, 2005. The samples were analyzed for MADEP-VPH, MADEP-EPH, VOCs using Method 8260B and SVOCs using EPA Method 8270C to determine whether excavation activities removed all the contaminated soil. The soil sample analytical results indicated all four sidewall samples and the floor sample were below the residential Maximum Soil Contaminant Concentration for all contaminants of concern. Based on results of the confirmation soil samples, all contaminated soil has been removed from the Former Building H-30 site.

If you require further information, please contact Mr. Andrew Smith, Environmental Quality Branch, Environmental Management Division, Installations and Environment Department, at (910) 451-9017.

Sincerely,

A handwritten signature in black ink, appearing to read "Scott Brewer".

SCOTT A. BREWER, PE
Director, Environmental Management
By direction of
the Commanding General

Enclosure: Former Building H-30 Soil Removal Report

5090/15

BEMD

Copy to: (w/o encl) *Cleveland*
NAVFACENGCOM (Mr. ~~Conway~~ Code OPCEV4)
Shaw (Mr. Ron Kenyon)